

Instructions for Using LJ-3036 Dowel-Fast Tap™

1. Mount the Dowel-Fast Tap™ in the Chuck-Buster™ (3031) or directly into the chuck of an electric drill motor.
2. With the Dowel-Fast Tap™ perpendicular to the surface, drill and tap the hole with one steady push of the drill. The tap portion of the Dowel-Fast Tap™ must go to the desired tap depth.
3. Reverse the drill motor and retract the Dowel-Fast Tap™.

